Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 9/11/2012, 9/12/2012, 9/13/2012	Man Days: 3
Inspection Unit: Springfield	•
Location of Audit: Springfield	
Exit Meeting Contact: Mark Mancewicz	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Charles Gribbins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION			
	CONSTRUCTION	INFORMATION	
Location of Construction:		Construction Performed By	<i>إ</i> :
Arlington & Berkley Drive, Springfield		Ameren Illinois Crew	
Contractor Foreman:	No contractors involve	d with this construction site.	
Operator Inspector:	Inspection conducted by Crew Leader.		
Person(s) On Job Site			
Mike Martinie			
Description of Construction:			
Replacing existing coupled steel main w	ith PE Main.		

MAIN INSTALLATION		Status
192.55	Steel	No
General Comment:	•	<u> </u>
The operator is replacing coupled	steel with PE.	
192.59	PE	Yes
General Comment:		•
The operator is installing PE Mail	n	
192.59	Other	No

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
There is no other type of pipe being installed at this loc	eation.	
192.5	Class location :	
General Comment:		
This is a class three location.		
192.619,192.621,192.623	MAOP	
General Comment:		
The MAOP of the new PE will be 60 psi		
192.63	Pipe Size :	
General Comment:		
2" PE		
192.55,192.59	Specification :	
General Comment:		
ASTM D2513		
192.55,192.59	Manufacturer :	
General Comment:		
Driscoplex		
192.55,192.59	Pipe Grade :	
General Comment:		
PE 2406		
192.55,192.59	Wall Thickness:	
General Comment:		
DR11		
192.63(a)(2)	Are pipe, valves, and fittings properly marked for identification?	
General Comment:		
Staff inspected the pipe and fittings at this construction	site.	
192.227	Date of Welder qualification:	Not Applicable
General Comment:		
This site was an all plastic installation and did not requ	ire a welder.	
192.227	Welder's Name:	
General Comment:		

AMEREN ILLINOIS COMPANY/9-13-2012

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

This site was an all plastic installation and did not require a welder.			
192.225,192.275,192.277,192.279,192.283	Is pipe joined in accordance with approved written procedures?	Satisfactory	
General Comment:			
Staff reviewed the joining procedures on site.			
192.285	Date of Plastic Joining Qualification :		
General Comment:			
1-27-2012			
192.285	Joiner's name:		
General Comment:			
Mike Martinie			
192.455	Is buried metallic pipe coated?	Not Applicable	
General Comment:			
No metallic pipe was being installed.			
192.461	Does coating meet 192.461?	Not Applicable	
General Comment:			
No metallic pipe was being installed; there was not a n	eed for coating.		
192.455(a)(1)	Is cathodic protection being provided?	Not Applicable	
General Comment:			
Cathodic protection not required an all plastic system.			
192.455(a)(1)	Is cathodic protection being provided? By Anodes:	Not Applicable	
General Comment:			
Cathodic protection not required an all plastic system.			
192.455(a)(1)	Is cathodic protection being provided? By Rectifier:	Not Applicable	
General Comment:			
Cathodic protection not required an all plastic system.			
192.461(c)	Is coating inspected just prior to being installed in the ditch?	Not Applicable	
General Comment:			
No metallic pipe was being installed; there was not a ne	eed for coating.		
192.467	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable	
<u>General Comment:</u>			

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Are above ground facilities cleaned and coated or jacketed as needed?  General Comment:  Staff did not observe any above ground facilities during this inspection.  192.303 Are comprehensive written construction specifications available and adhered to?  General Comment:  The construction specifications were reviewed onsite and then verified by observation.  192.305 Are inspections performed by the operator to check adherence to the construction specifications?  Staff verified this section by asking questions and observing how the pipe was installed.  192.307 Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?  General Comment:  Staff verified this section by asking questions and observing how the pipe was installed.  192.307 Is material being visually inspected at the site of installation to ensure against damage that could impair its satisfactory serviceability?  General Comment:  Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.  192.319 Is ditch back-filled to provide firm support and prevent damage to pipe or coating?  General Comment:  Staff did not observe the backfilling of the main at this site.  192.321(c) Is plastic pipe installed as to minimize shear and tensile Satisfactory orces?  General Comment:  The operator had most of the plastic pipe installed prior to staffs amival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the dich. In the dich. In the most of the plastic pipe installed prior to staffs amival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the dich. The was noted at all location where the pipe was left exposed to make service line connections.  192.3215  Are required clearances from underground structures  Satisfactory being maintained?  General Comment:  Staff dat n	No metallic pipe was being installed; there was not a n	eed for electrical isolation.	
Staff did not observe any above ground facilities during this inspection.  192,303	192.479		Not Applicable
Are comprehensive written construction specifications available and adhered to?  General Comment:  The construction specifications were reviewed onsite and then verified by observation.  192.305 Are inspections performed by the operator to check adherence to the construction specifications?  General Comment:  Staff verified this section by asking questions and observing how the pipe was installed.  192.307 Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?  General Comment:  Staff was not orisite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not interest when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.  192.319 Is disch back-filled to provide firm support and prevent damage to pipe or coating?  General Comment:  192.321(c) Is plastic pipe installed as to minimize shear and tensile forces?  General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the disch.  192.321(e) Does plastic pipe have means of locating while underground?  General Comment:  Tracer wise was noted at all location where the pipe was left exposed to make service line connections.  Are required clearances from underground structures  Satisfactory  General Comment:  Staff was not on site when the operator crossed other underground structures but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure to type of	General Comment:		
available and adhered to?   Satisfactory	Staff did not observe any above ground facilities during	g this inspection.	
The construction specifications were reviewed onsite and then verified by observation.  192.305  Are inspections performed by the operator to check adherence to the construction specifications?  Staff verified this section by asking questions and observing how the pipe was installed.  192.307  Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?  General Comment:  Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.  192.319  Is ditch back-filled to provide firm support and prevent damage to pipe or coating?  General Comment:  Staff did not observe the back/filling of the main at this site.  192.321(c)  Is plastic pipe installed as to minimize shear and tensile forces?  General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the dichn.  192.321(e)  Does plastic pipe have means of locating while underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  Are required clearances from underground structures  Satisfactory  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of Satisfactory	192.303		Satisfactory
Are inspections performed by the operator to check adherence to the construction specifications?  Staff verified this section by asking questions and observing how the pipe was installed.  192.307 Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?  General Comment:  Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.  192.319 Is ditch back-filled to provide firm support and prevent damage to pipe or coating?  General Comment:  Staff did not observe the backfilling of the main at this site.  192.321(c) Is plastic pipe installed as to minimize shear and tensile forces?  General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the diction.  192.321(e) Does plastic pipe have means of locating while underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  Are required clearances from underground structures being maintained?  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug al locations where they had to cross underground structure.  Satisfactory  Satisfactory  Is required cover being obtained appropriate to type of	General Comment:		
Adherence to the construction specifications?  Satisfactory  General Comment:  Staff verified this section by asking questions and observing how the pipe was installed.  192.307  Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?  Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.  Is ditch back-filled to provide firm support and prevent damage to pipe or coating?  General Comment:  Staff did not observe the backfilling of the main at this site.  192.321(c)  Is plastic pipe installed as to minimize shear and tensile forces?  General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the ditch.  192.321(e)  Does plastic pipe have means of locating while underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  Are required clearances from underground structures being maintained?  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground appropriate to type of  Satisfactory  Is required cover being obtained appropriate to type of	The construction specifications were reviewed onsite a	and then verified by observation.	
Staff verified this section by asking questions and observing how the pipe was installed.  192.307 Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?  General Comment:  Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.  192.319 Is ditch back-filled to provide firm support and prevent damage to pipe or coating?  General Comment:  Staff did not observe the backfilling of the main at this site.  192.321(c) Is plastic pipe installed as to minimize shear and tensile forces?  General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the ditch.  192.321(e) Does plastic pipe have means of locating while underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325 Are required clearances from underground structures being maintained?  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327 Is required cover being obtained appropriate to type of	192.305		Satisfactory
Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?    General Comment:   Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.	General Comment:		
installation to ensure against damage that could impair its serviceability?    Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.    192.319	Staff verified this section by asking questions and observed	erving how the pipe was installed.	
Staff was not onsite when the operator performed the visual inspection. Staff did question the operator about the inspection the operator stated that they did not find any damages that would impair its serviceability.  192.319	192.307	installation to ensure against damage that could impair its	Satisfactory
192.319   Is ditch back-filled to provide firm support and prevent damage to pipe or coating?   Not Checked	General Comment:		
General Comment:  Staff did not observe the backfilling of the main at this site.  192.321(c) Is plastic pipe installed as to minimize shear and tensile forces?  General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the ditch.  192.321(e) Does plastic pipe have means of locating while underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325 Are required clearances from underground structures being maintained?  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327 Is required cover being obtained appropriate to type of Satisfactory		visual inspection. Staff did question the operator about the inspection the o	perator stated that they did not
Staff did not observe the backfilling of the main at this site.  192.321(c) Is plastic pipe installed as to minimize shear and tensile forces?  General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the ditch.  192.321(e) Does plastic pipe have means of locating while underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325 Are required clearances from underground structures being maintained?  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  Is required cover being obtained appropriate to type of	192.319	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Not Checked
Is plastic pipe installed as to minimize shear and tensile forces?    Satisfactory	General Comment:		
General Comment:  The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the ditch.  192.321(e)  Does plastic pipe have means of locating while underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325  Are required clearances from underground structures being maintained?  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of  Satisfactory	Staff did not observe the backfilling of the main at this	site.	
The operator had most of the plastic pipe installed prior to staff's arrival. Most of the pipe was installed by boring and a weak link was used to pull the pipe into the ditch.  192.321(e)  Does plastic pipe have means of locating while underground?  Satisfactory  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325  Are required clearances from underground structures being maintained?  Satisfactory  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of	192.321(c)		Satisfactory
the ditch.  192.321(e)  Does plastic pipe have means of locating while underground?  Satisfactory  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325  Are required clearances from underground structures being maintained?  Satisfactory  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of	General Comment:		
underground?  General Comment:  Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325  Are required clearances from underground structures being maintained?  Satisfactory  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of  Satisfactory		r to staff's arrival. Most of the pipe was installed by boring and a weak link	was used to pull the pipe into
Tracer wire was noted at all location where the pipe was left exposed to make service line connections.  192.325  Are required clearances from underground structures being maintained?  Satisfactory  Satisfactory  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of	192.321(e)		Satisfactory
Are required clearances from underground structures being maintained?  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of	General Comment:		
being maintained?  General Comment:  Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327  Is required cover being obtained appropriate to type of  Satisfactory  Satisfactory	Tracer wire was noted at all location where the pipe wa	as left exposed to make service line connections.	
Staff was not on site when the operator crossed other underground structures, but staff did question the operator about the underground structures and was advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327 Is required cover being obtained appropriate to type of	192.325		Satisfactory
advised by the crew leader that they hand dug at locations where they had to cross underground structure.  192.327 Is required cover being obtained appropriate to type of Satisfactory	General Comment:		
			rground structures and was
	192.327		Satisfactory

AMEREN ILLINOIS COMPANY/9-13-2012

Page 4 of 6

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
At several of the locations staff had the o top of the pipe to ground level.	perator take a measurement to verify the depth of the pipe, at both locations the depth	was approximately 34" from the
192.503	Are general testing requirements being met?	Not Checked
General Comment:	<u> </u>	
Staff did not stay on site to observe the p	ressure testing.	
192.517	Are records being made of strength and leak tests?	Not Checked
General Comment:	<u> </u>	
Staff did not review pressure test records	at this location.	
192.807	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
General Comment:	·	
Staff reviewed Qualification records for M	like Martinie	
192.805(c)	Were non-qualified personnel being "directed and observed" by a qualified individual?	Not Checked
General Comment:	<u> </u>	•
There were not any non-qualified person.	nel on the job site.	
192.805(c)	Were span of control limitations being followed?	Not Checked
General Comment:	<u> </u>	•
There were not any non-qualified person.	nel on the job site.	
Was a Protocol 9 (Form 15) Com	pleted?	Yes
General Comment:		
See Operator Qualification Field Inspecti	on Protocol Form for this information.	
192.614	Were One Call Notifications performed as required?	Satisfactory
General Comment:		
Staff reviewed the one call dig tickets and	d then verified some of the markings.	
192.614	Dig Ticket #	X002430610X002430563
General Comment:	-	
The following did numbers were reviewed	d: X002430610 & X002430563	

MAIN INSTALLATION CHECKLIST Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.